

Automatic

Beitrag von „Fortunato Imbes“ vom 7. Januar 2011 um 09:14

when restart, the problem disappears.

The problem happens when start the motor and quickly inserts the automatic on D.