

Luftfederung

Beitrag von „b1971“ vom 7. Januar 2018 um 19:40

Hallo,

ich hatte ein ähnliches Problem mit meinem T2. Als ich am Fr. meinen Touareg für die Rückreise aus dem Ski Urlaub klarmachte, bekam ich die Fehlermeldung "Stop! Fehler Fahrwerk" angezeigt. Ein löschen des Fehlers über VCDS half nicht. Da sich das Fahrzeug auf gleichmäßiger Höhe im Offroad Niveau befand und weich abfederte, bin ich trotzdem die 950km gemütlich nach Hause gefahren...

Heute habe ich festgestellt, dass die Sicherung (40A) für den Kompressor durch war. Nachdem ich die ausgetauscht habe, war wieder alles in Ordnung...

Aber: Was kann die Ursache dafür sein? Ich hätte ein besseres Gefühl, wenn ich wüsste warum die Sicherung durchgebrannt ist.

Viele Grüße,
Bernd

VCDS Fehler:

Address 34: Level Control (J197) Labels:. 7P0-907-553.clb

Part No SW: 7P0 907 553 N HW: 7P0 907 553 N

Component: PASM H01 1550

Revision: 00000000 Serial number: 00000122470430

Coding: 14210001

Shop #: WSC 31414 790 00001

ASAM Dataset: EV_PASMConti 001004

ROD: EV_PASMConti.rod

VCID: 42B37B08D56B1256C7-8016

1 Fault Found:

0644 - Level control system

C10D3 07 [008] - Mechanical Failure

Intermittent - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 9

Fault Frequency: 85

Reset counter: 1

Mileage: 330752 km

Date: 2019.02.26

Time: 30:05:05

Default: 60

Default: 8E

Default: 00