Foot on the brake required to start the car.

Beitrag von "agroetsch" vom 22. März 2005 um 16:34

Hello,

this is the normal behaviour for the actual models, i think since the 2005 models.

It has nothing to do with keyless access.

Don't worry about that!