

Fehlzüendungen V6 FSI 2012

Beitrag von „OldGrumpy“ vom 15. Oktober 2014 um 21:31

Hallo!

Nach langer Abwesenheit melde ich mich mal wieder....

Folgendes Problem ist seit gestern am Dicken aufgetreten:

Bei Kaltstart ruckelt der Motor extrem und es dauert knapp 30Sec bis die Leerlaufdrehzahl sich stabilisiert und rund laeuft.

Sobald der Motor mal warm war passiert das nicht mehr und er laeuft rund.

VCDS Readout habe ich gemacht.

Hier der erste Teil:

5 Faults Found:10203 - Random/Multiple Cylinder Misfire DetectedP0300 00 [036] - - Intermittent - Not Confirmed - Tested Since Memory ClearFreeze Frame:Fault Status: 00000001Fault Priority: 2Fault Frequency: 1Mileage: 60246 kmDate: 2014.10.14Time: 15:45:5710595 - Cylinder 5P0305 00 [036] - Misfire DetectedIntermittent - Not Confirmed - Tested Since Memory ClearFreeze Frame:Fault Status: 00000001Fault Priority: 2Fault Frequency: 1Mileage: 60246 kmDate: 2014.10.14Time: 15:46:4910596 - Cylinder 6P0306 00 [036] - Misfire DetectedIntermittent - Not Confirmed - Tested Since Memory ClearFreeze Frame:Fault Status: 00000001Fault Priority: 2Fault Frequency: 1Mileage: 60246 kmDate: 2014.10.14Time: 15:46:49VCDSDiagnostic Trouble Code ReportControl Module Part Number: 03H 906 023 AGPage 210592 - Cylinder 2P0302 00 [036] - Misfire DetectedIntermittent - Not Confirmed - Tested Since Memory ClearFreeze Frame:Fault Status: 00000001Fault Priority: 2Fault Frequency: 1Mileage: 60246 kmDate: 2014.10.14Time: 15:46:4910594 - Cylinder 4P0304 00 [036] - Misfire DetectedIntermittent - Not Confirmed - Tested Since Memory ClearFreeze Frame:Fault Status: 00000001Fault Priority: 2Fault Frequency: 1Mileage: 60246 kmDate: 2014.10.14

Time: 15:46:49

Danach habe ich die das Modul 01 ausgelesen und individuelle Parameter selektiert. Folgendes habe ich gefunden.

Address 01: Engine (03H 906 023 AG)

08:23:05

141 Misfires per 1000 revolutions of cylinder 1 0

142 Misfires per 1000 revolutions of cylinder 2 0

143 Misfires per 1000 revolutions of cylinder 3 0

144 Misfires per 1000 revolutions of cylinder 4 0

145 Misfires per 1000 revolutions of cylinder 5 0

146 Misfires per 1000 revolutions of cylinder 6 0

158 Number of misfires; cylinder 1 554

159 Number of misfires; cylinder 2 6013

160 Number of misfires; cylinder 3 522

161 Number of misfires; cylinder 4 1162

162 Number of misfires; cylinder 5 477

163 Number of misfires; cylinder 6 852

Kann es sein das sich bei mir die Zuendspulen einen Fehler haben?

Ich finde keinen anderen Fehlercode und auch die Kabel sind nicht beschaedigt.

Zuendspule kosten knapp 23EUR/Stk.

Was ist Eure Meinung.

Der 😊 will das Steuergeraet wechseln und pauschal den Kabelbaum zur Zuendkerze ersetzen.
Ich finde das ist der falsche Weg zumal ich knapp aus der Garantie raus bin und auf Kulanz
hoffen muss.

Danke fuer Eure Postings!!!

Matt