

Geber für Abgastemperatur G235 defekt

Beitrag von „Elkoss“ vom 6. Februar 2017 um 08:35

[Zitat von Elkoss](#)

Hello,

Sorry for writing in english... I have used Google translate to understand your posts. I have VW Touareg 3.0 V6 TDI (2006) with engine type BKS. My problem is similar to yours. Car is in Limp mode - no power, slow driving. The only error in VCDS is DPF filter clogged. I tried to see some more parameters and VCDS shows 102.1 at constant value of 899 degrees Celsius.

Well, the sensor was exchanged with original VW part 059 906 088 A. We started the car, clear the error messages, but 102.1 is still showing 899 degrees Celsius.

The car can't perform DPF filter regeneration...

Any idea how to reset 102.1 in ECU??

Thank you in advance!

Jure

Alles anzeigen

Hello

Just for your information in case you have similar symptoms with your Touareg. Sensor G235 - Exhaust gas temperature (after turbo charger) is not showing correct values in VCDS in Bank 102.1 When you observe the value, it will constantly show the value of 899 degrees Celsius. It is now confirmed, that 102.1 is not relevant bank for sensor G235. The value is not mapped correctly!

All the best!

Jure