

Heckklappe Touareg 7P BJ 2014 - Wasser im Heck und komische Geräusche ???

Beitrag von „Mosanu“ vom 11. Februar 2021 um 14:22

Deutsche Version nach Englisch.

I confirm that the entry point is the central stop light, somewhere in the middle of the lower part.

I have ordered replacement seal and also a stop light (around 80 euro). The problem is that I tried to remove the light and I couldn't, so I will ask the dealer to help me.

As a precautionary measure, I will also ask them to apply a thin layer of sealer over the new seal.

Ich bestätige, dass der Einstiegspunkt das zentrale Bremslicht ist, irgendwo in der Mitte des unteren Teils.

Ich habe Ersatzdichtung und auch eine Bremsleuchte (ca. 80 Euro) bestellt. Das Problem ist, dass ich versucht habe, das Licht zu entfernen, und ich konnte es nicht. Deshalb werde ich den Händler bitten, mir zu helfen.

Als Vorsichtsmaßnahme werde ich sie auch bitten, eine dünne Schicht Versiegelung auf die neue Versiegelung aufzutragen.