

Auspuffendrohr verrußt

Beitrag von „haimik“ vom 20. Februar 2025 um 19:06

Address 01: Engine (7P1 907 401 E)

09:25:12

IDE00365 Injection quantity deviation cylinder 1 0.26 mg/stroke

IDE00366 Injection quantity deviation cylinder 2 0.73 mg/stroke

IDE00367 Injection quantity deviation cylinder 3 0.01 mg/stroke

IDE00368 Injection quantity deviation cylinder 4 -0.37 mg/stroke

IDE00369 Injection quantity deviation cylinder 5 -0.37 mg/stroke

IDE00370 Injection quantity deviation cylinder 6 -0.25 mg/stroke