

# **Foot on the brake required to start the car.**

**Beitrag von „agroetsch“ vom 22. März 2005 um 16:34**

Hello,

this is the normal behaviour for the actual models, i think since the 2005 models.

It has nothing to do with keyless access.

Don't worry about that!