

Ausstattung des 2006 Dicken in USA

Beitrag von „dschlei“ vom 23. April 2005 um 01:41

Frisch aus der Presse! Die Ausstattungsversionen des 2006 Dicken in Amiland!

Ihr werdet dann Gleiches vielleicht etws später bekommen, wie beim DVD Navi vielleicht! 🗣️

Hannes muss das dann alles übersetzen! 😄

V6 3.2L 240 6AT w/ Tiptronic August

V6 3.6L UPGRADED 276 6AT w/ Tiptronic December

V8 4.2L 310 6AT w/ Tiptronic August

S = Standard, O = Option, OP = Optional Package

New Features and Changes V6 V8

Special Order Program no longer available -- --

3.6L V6 4-valve FSI engine upgrade to estimated 276 hp (36 hp increase from 3.2L engine) - delayed introduction

S --

V8 Equipment Package #4 no longer available -- --

V8 Equipment Package #5 renamed as #4 -- OP

Electronic Parking Assistance added to V6 Equipment Package #3 OP --

Electronic Parking Assistance added to V8 Equipment Package #s 2, 3, and 4 -- OP

Rear Differential Lock added to V8 Equipment Package #3 -- OP

Roof rack cross bars no longer available on V6 or V8. They are now available as part of the Accessories program. -- --

Black tracks in roof are standard on V6 S --

Chrome tracks in roof are standard on V8 -- S

New roof antenna for improved key fob performance S S

Rearview camera and auxiliary audio connector added to the optional Navigation system OP OP

Rearview camera and auxiliary audio connector added to V6 Equipment Package #4, consequently to V6 Equipment Package #5 OP OP

Rearview camera and auxiliary audio connector added to V8 Equipment Package #s 2 and 3 OP OP

VW Telematics by OnStar no longer available -- --

Servotronic standard on V8 -- S

Servotronic standard on 3.6L V6 - delayed introduction S S

Power lift gate added to V6 Equipment Package #5 and V8 Equipment Package #4 - delayed introduction OP OP

Interior carpet from "Tuft" replaces "Perlvelour" S S
Floor mats from "Tuft" replaces "Perlvelour" (V6 only) S --
Chrome trim replaces wood trim on transmission gear shift lever S S
Replace spare tire storage cover holder w/ latch on rear seatbacks S S
Four stitching leather steering wheel replaces one stitching steering wheel S S
Storage compartment under passenger seat no longer available S S
115V power outlet replaces 12V power outlet in cargo area S S

PER VWWEBSOURCE