

## **Need help finding correct part number**

**Beitrag von „spockcat“ vom 8. Juni 2004 um 18:55**

Roland,

There is a hole in front of the flashlight and to the right of the shift lever. I have been told this is to shut off the passenger airbag. We do not have this option in the USA and thus we cannot have this hole in the wood trim. You have confirmed that the code 4UE will get a wood trim with this hole.

Still looking for wood trim without this hole.

Jim