

# Foot on the brake required to start the car.

**Beitrag von „dschlei“ vom 22. März 2005 um 17:53**

This was spawned by the US Safety Regulations. All manufacturers that export their vehicles to the US have this "wonderfull feature".

Once you are used to it, it is not much of a bother. I have to do it now for over 15 years. It was started with Audi's problem of unintended exhilaration upon vehicle start-up. 🤖