

# IPod

**Beitrag von „agroetsch“ vom 11. April 2005 um 14:56**

Hallo,

für alle iceLink-plus Nutzer, da gibt es ein Update auf Version 2.06

Neu ist vor allem die doppelt so große Anzeige der Titel im Display!

Jetzt müsste nur im iceLink Modus auch noch das Album Cover angezeigt werden wie im "Normalmodus" 😞

Zitat

2.06

Firmware upgrade recommended for the following car interfaces and users:

- SONY
- C2 + SONY (OEM headunits with Connects2 adapter)
- BECKER
- KENWOOD
- MERCEDES
- BLAUPUNKT
- Alfa Romeo (Alfa 147, 156)
- **VW/AUDI** - iPod Photo users
- AUDI
- **VOLKSWAGEN**

New features:

- Double size display characters on iPod while displaying song informations.

Bug fixes:

- Corrected menu acces with OEM HU + C2 adapters. The previous versions switched off ice>Link Menu after 2 seconds.
- Fixed Kenwood and Mercedes freezing problem. With earlier versions the HU refused the ice>Link after some weeks.
- Corrected Blaupunkt interface. Now compatible with DX-... navigation HU-s.
- Fixed Blaupunkt communication interface. The previous versions froze at engine start. Now fully compatible with ALFA ROMEO 147 headunits.
- Fixed Blaupunkt functional problems around track step.

- Fixed VW/AUDI Pause problem at ignition/radio off. The previous versions sometimes left the iPod in play state after radio power off.
- Modified SONY/BECKER communication interface. Now compatible with PORSCHE CDR-220 (tested), and maybe with CDX-F5000 serie.

Alles anzeigen

[Quelle](#) | [Download](#) | [Anleitung](#)