

Akustische Bestätigung der Zentralverriegelung

Beitrag von „Franks“ vom 11. Oktober 2005 um 01:02

So, hier mal der Scan meines Toaureg, bei dem ich im Menü des Bordcomputers den Amschliess- Chirp ein- und ausschalten kann.

Ich habe übrigens alle Ländereinstellungen auf Deutschland bzw. Europa umgestellt, damit diese ganzen Warntöne weg sind.

Zitat

Monday, 10 October 2005, 17:37:04

VAG-COM Version: Release 504.1-UD

Chassis Type: 7L - VW Touareg

Scan: 01 02 03 05 06 08 09 11 15 16 17 18 19 1C 22 29 34 36 37 39
45 46 47 55 56 65 68 6E 77

Address 01: Engine

Controller: 4D0 907 560 DB

Component: 4.2L V8/5V G 0020

Coding: 0007875

Shop #: WSC 31414

No fault code found.

Readiness: 0000 0000

Address 02: Auto Trans

Controller: 09D 927 750 AQ

Component: AL 750 6A 0580

Coding: 0004153

Shop #: WSC 31414

No fault code found.

Address 03: ABS Brakes

Controller: 7L0 907 379 G

Component: ESP ALLRAD MK25 0203

Coding: 0014594

Shop #: WSC 31414

No fault code found.

Address 05: Acc/Start Auth.
Controller: 3D0 909 135 R
Component: 17 Kessy 6610
Coding: 0131304
Shop #: WSC 31414
No fault code found.

Address 06: Seat Mem. Pass
Controller: 7L0 959 760
Component: Sitzverstellung 0701
Coding: 0000000
Shop #: WSC 00000
No fault code found.

Address 08: Auto HVAC
Controller: 7L6 907 040 L
Component: CLIMAtronic R/L 4017
Coding: 0020030
Shop #: WSC 31414
No fault code found.

Address 09: Cent. Elect.
Controller: 7L6 937 049 M
Component: 3001
Coding: 0105694
Shop #: WSC 31414
No fault code found.

Skipping Address 15-Airbags

Address 16: Steering wheel
Controller: 7L6 953 549 E
Component: Lenksäulenmodul 3301
Coding: 0000232
Shop #: WSC 31414
No fault code found.

Address 17: Instruments
Controller: 7L6 920 981
Component: KOMBIINSTRUMENT RB8 3110
Coding: 0005131
Shop #: WSC 31414
No fault code found.

Address 19: CAN Gateway
Controller: 6N0 909 901
Component: Gateway K<>CAN 0101
Coding: 0000006
Shop #: WSC 31414
No fault code found.

Address 1C: Position Sensing
Controller: 7L6 919 879 A
Component: JCI PathPoint 2200
Coding: 0000000
Shop #: WSC 00000
No fault code found.

Address 22: AWD
Controller: 0AD 927 755 AJ
Component: TRANSFERCASE 0100
Coding: 0000000
Shop #: WSC 00000
No fault code found.

Address 29: Left Light
Controller: 3D0 909 157
Component: EVG GDL+AutoLWR(I) 0001
Coding: 0000003
Shop #: WSC 31414
No fault code found.

Address 34: Level Control

Controller: 7L0 907 553 F
Component: LUFTFDR.-CDC- 3C3P1 3081
Coding: 0015521
Shop #: WSC 31414
No fault code found.

Address 36: Seat Mem. Drvr
Controller: 7L0 959 760
Component: Sitzverstellung 0701
Coding: 0000000
Shop #: WSC 00000
No fault code found.

Address 37: Navigation
Controller: 7L6 919 887 C
Component: Navigation 0814
Coding: 0000101
Shop #: WSC 31414
1 Fault Found:
02731 - CD Reading Error
001 - Upper Limit Exceeded - Intermittent

Address 39: Right Light
Controller: 3D0 909 158
Component: EVG GDL+AutoLWR(r) 0001
Coding: 0000003
Shop #: WSC 31414
No fault code found.

Address 46: Central Conv.
Controller: 7L0 959 933 E
Component: 2L HSG 0201
Coding: 0000085
Shop #: WSC 31414
1 Fault Found:
00932 - Electric Window Motor; Drivers Side (V147)
005 - No or Incorrect Basic Setting / Adaptation - Intermittent

Address 47: Sound System
Controller: 7L6 035 456
Component: 08K Audioverst. 0105
Coding: 0000000
Shop #: WSC 00000
No fault code found.

Address 56: Radio
Controller: 7L6 035 186 A
Component: Radio 0814
Coding: 0004042
Shop #: WSC 31414
No fault code found.

Address 68: Wiper Electr.
Controller: 7L0 955 119 K
Component: Front Wiper 4027
Coding: 0000855
Shop #: WSC 31414
No fault code found.

Address 6E: Ctrl Head Roof
Controller: 7L6 919 044 K
Component: DACHDISPLAY 0538
Coding: 0000000
Shop #: WSC 31414
No fault code found.

End -----

Alles anzeigen

Gruß,

Frank